SAUKVILLE ELEMENTARY SCHOOL: BUILDING SYSTEMS SUMMARY

The following is summary of Plumbing, HVAC and Electrical needs. This is not intended to be a comprehensive list, but a summary of existing building system needs and possible recommendations as identified by the engineering team. Full engineers' reports are located later in this document.

Saukville Elementary School	Analysis	Recommendations
Building Systems		
Plumbing		
Domestic Water		
Water Service	Water Service includes 6" Ductile Iron water service with a 2" water meter. Items are located on the main level and 1.5" Copper water service with 1" water meter. Both with bypass piping and a water softener and located on the tunnels.	
Water Distribution Piping	Three pipe system is uninsulated copper with areas of galvanized piping. Domestic cold water piping system is in poor condition. Domestic hot water return piping system is in poor condition. Backflow preventers are in fair condition.	Backflow preventer shall be maintained, repaired, and tested. Galvanized piping in shal be replaced. Repair all leaks, insulate, and provide properly sized system. Piping shall be routed above floor.
Fire Sprinkler System	There is no automatic fire sprinkler system in the building.	Existing water service is capable of supporting an automatic fire sprinkler system, but testing i required.
Sanitary and Storm Piping		
Sanitary Waste	Sewer includes the following: Sewer lateral discharging to the local municipal sewage utility. There is not a backwater valve on the sewer lateral.	
Sanitary Waste and Vent Piping	System material is Cast Iron, Galvanized & PVC. Sanitary piping system is in poor condition. The lower lever drainage system is in poor condition. Solid waste interceptors are not present that serves the art sinks. They are in fair condition.	Repair leaks, inspect system, and provide maintenance. All clay, cast iron, and galvanized piping shall be replaced. Provide properly sized system.
Kitchen Equipment	Grease waste piping system or grease interceptor were located in the building. Natural gas system pressure is 1/2 pounds without the need of regulators. Welding gas system consists of portable gas cylinder charts.	Provide a grease interceptor for kitchen sink pe the Wisconsin plumbing code.
Storm System	Sewers are Cast Iron & Galvanized in poor condition with lateral discharging to the local municipal storm piping and no backwater valve. Interior roof drain and conductor piping discharges to storm drainage system and to grade. Exterior rain gutters discharge to grade storm sewer. The lower level and tunnels are served by two sump pumps in fair condition.	Repair leaks, inspect piping, replace problem areas, insulate, and provide maintenance. Cast iron and galvanized piping shall be replaced. Provide properly sized system.
Plumbing Equipment		
Gas Water Heater	2qty. Main Level – 60 gallon. Lower Level / Tunnel – 40 gallon. 120 degree storage temperature, in fair condition. The main level gas water heater is located in a difficult area.	Provide equipment for new building addition and domestic hot water piping with balancing valves.
Electric Water Heater	2 qty. NW area – 40 gallon. SW area – 40 gallon. 120 degree storage temperature, in fair condition.	
Water Softener	2qty. Main Level - 75gpm. Lower Level / Tunnel - 50gpm, in fair condition.	
Circulating Pumps	3qty. Main Level – 8gpm. NW – 5gpm. SW – 5gpm, in poor condition.	
Sanitary Ejector and Pump	1qty. 40 gpm, in poor condition	Provide sanitary ejector pump(s).
Clear Water Sump and Pump	2qty. 40 gpm, in poor condition.	Provide new clear water pump(s).
Plumbing Fixtures		
Plumbing Fixtures		Provide senor operated valves and faucets, ne fixtures and trim, wall mounted fixtures, and floor drains. Replace non-ADA compliant fixtures with ADA compliant ones.
Water Closets	Water Closets are mix of floor mount with tanks or flush valves. Flush valves are manual and sensor operated. The majority of fixtures are in poor condition and ADA compliant.	
Lavatories	Lavatories are mix of wall mount with faucets are manual lever. The majority of the fixtures are in fair condition, ADA compliant, and not at child height.	



Saukville Elementary School	Analysis	Recommendations
Plumbing		
Lavatory Wash Stations	Lavatory Wash Stations are sensor battery operated. The majority of the fixtures are in fair condition and ADA compliant.	
Urinals	Urinals are mix of floor mount and wall mount with flush valve. Flush valves are manual and sensor battery operated. The majority of the fixtures are in fair condition and ADA compliant.	
Electrical Water Coolers	Electrical Water Coolers are a mix of with and without bottle filling stations. The majority of the fixtures are in fair condition, ADA compliant, and not at child height.	
Sinks - General	The majority of the fixtures are in poor condition and not ADA compliant.	
HVAC		
Heating System		
Boiler Plant	The building is served by three Thermal Solutions hot water boilers each rated at 1,320,000 btu gross output, installed in 2013, and in excellent condition. The ASHRAE service life expectancy s is about 20-25 years.	Continue preventative maintenance. They should continue to serve the building for another 15-20 years.
Piping and Pumping	The piping and pumping system is a primary-secondary variable flow arrangement, in excellent condition, and served by variable frequency drives. A stand-by pump is in place. The ASHRAE service life is about 20-25 years.	Continue preventative maintenance. They should continue to serve the building for another 15-20 years.
Ventilation and Air Conditioning Systems		
Air Handling Units	Served by classroom unit ventilators, packaged rooftop units, and indoor air handling units. The original indoor air handling equipment has been well maintained and is in fair condition.	Continue with the current maintenance program on all air handling equipment.
	Six classrooms are served by new unit ventilators, installed in 2013, that contain hot water heating and direct-expansion cooling coils. The direct-expansion cooling coils are piped to residential-style condensing units on the roof.	
	The multi-purpose room is served by a vertical constant volume indoor air handling unit that was converted to hot water in 2013. The vertical air handling unit is within a small storage room and is not easily accessible for maintenance.	
	The gymnasium is served by a heating-only indoor air handling unit with pneumatic control.	
	A classroom addition is served by an indoor constant volume air handling unit. The cooling coil is piped to a roof-mounted Trane condensing unit. The units are in excellent condition and should continue to serve for another 15-20 years.	Plans should be made to replace the indoor equipment and upgrade all constant volume systems to VAV systems. All duct-mounted hot water booster coils would be replaced with VAV boxes with hot water reheat coils.
	The office area is served by a Lennox gas-fired packaged rooftop unit, installed in 2007, with direct-expansion cooling. They appear to be in good condition. The Lennox unit should serve the office are for another 5-10 years. The Trane units should serve the building for another 10-15 years.	
	The rest of the classrooms are served by two Trane 35-ton cooling- only packaged rooftop units. The outdoor condensing unit serving the indoor classroom air handling unit appears to be about 10-15 years old. The unit is in good condition and should continue to serve for another 10-15 years.	To address the current COVID-19 situation as well as future health concerns, we recommend installing bipolar ionization equipment within all existing air handling units.
Control Systems		
System	The building is served by a mixture of control system, including a Trend digital control system, Johnson Controls digital control system, ASI digital control system, and a pneumatic control system.	The system should be upgraded to a complete digital control system of a single manufacturer.

SAUKVILLE ELEMENTARY SCHOOL: BUILDING SYSTEMS SUMMARY

Electric Service The service is 1,600 amp 208Y/120 volt 3-phase 4-wire. The main switchboard is a Square D, installed in 1974, and in the Electrical Room. The transformer is outside the Custodial Room, while the meter is inside. The CT's are inside the transformer. The maximum demand on the service is 134 KWs. There is no surge protection device. Panelboards The panelboards in the newer areas are Square D. The panelboards in the older areas are Cutler Hammer. A majority of the panelboards are full. Generator This building does not have a generator. Add an emergency generator and transfer switch to power life sate in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. There Provide ultrasonic occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts in 2012. There Provide ultrasonic occupancy sensors.	ditions are ed. Provide n service.
The service is 1,600 amp 208Y/120 volt 3-phase 4-wire. The main switchboard is a Square D, installed in 1974, and in the Electrical Room. The transformer is outside the Custodial Room, while the meter is inside. The CT's are inside the transformer. The maximum demand on the service is 134 KWs. There is no surge protection device. Panelboards The panelboards in the newer areas are Square D. The panelboards in the older areas are Cutler Hammer. A majority of the panelboards are full. Generator This building does not have a generator. The classrooms have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2 switches to control separate rows. The company of the panelboard sautomatic lighting shut-service of this fadequately sized. If building added, an upgrade will be required surge protection device on main adequately sized. If building added, an upgrade will be required surge protection device on main device. The panelboards in the newer areas are Square D. The panelboards are in good Additional panelboards can be added to learn any control of the panelboards. The newer panelboards are in good Additional panelboards are full. Add an emergency generator and transfer switch to power life sate that the provide dual technology occupants in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts in 2012. There	ditions are ed. Provide n service.
Switchboard is a Square D, installed in 1974, and in the Electrical Room. The transformer is outside the Custodial Room, while the meter is inside. The CT's are inside the transformer. The maximum demand on the service is 134 KWs. There is no surge protection device on mai device. Panelboards The panelboards in the newer areas are Square D. The panelboards in the older areas are Cutler Hammer. A majority of the panelboards are full. Generator This building does not have a generator. Add an emergency generator and transfer switch to power life sale transfer switch to power life sale in 2012. Classrooms have 2x4 acrylic lens 2-lamp or 4-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There	ditions are ed. Provide n service.
The panelboards in the newer areas are Square D. The panelboards in the older areas are Cutler Hammer. A majority of the panelboards are full. Generator This building does not have a generator. Light Fixtures & Controls The classrooms have 2x4 acrylic lens 2-lamp or 4-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic hallasts in 2012. There were converted to T8 lamps and electronic hallasts in 2012. There	
in the older areas are Cutler Hammer. A majority of the panelboards are full. Generator This building does not have a generator. Light Fixtures & Controls The classrooms have 2x4 acrylic lens 2-lamp or 4-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There	
This building does not have a generator. **Add an emergency generator and transfer switch to power life sate transfer switch transfer switch to power life sate transfer switch transfe	
Light Fixtures & Controls The classrooms have 2x4 acrylic lens 2-lamp or 4-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There were converted to T8 lamps and electronic ballasts in 2012. There	
The classrooms have 2x4 acrylic lens 2-lamp or 4-lamp fixtures. Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures were converted to T8 lamps and electronic ballasts Provide dual technology occupant automatic lighting shut-	
Classrooms Existing fixtures were converted to T8 lamps and Electronic ballasts in 2012. Classrooms have 2 switches to control separate rows. The rooms have no occupancy sensors. Corridors have 2x4 acrylic lens 2-lamp fixtures. Existing fixtures Were converted to T8 lamps and electronic ballasts in 2012. There	
were converted to T8 lamps and electronic ballasts in 2012. There Provide ultrasonic occupancy s	
Corridors are 3-way switches for manual control. Corridor has 24/7 night light corridors. fixtures and no occupancy sensors.	ensors in
Gymnasium The gym has new 6-lamp high bay fixtures with T8 lamps.	
Building mounted canopy fixtures are metal halide and wall packs Exterior Lighting are LED. There is one utility pole light to serve the parking lot. The exterior lighting is controlled from the BAS. Provide new pole mounted LED are the parking lot.	a lighting for
Emergency Egress Lighting There are fluorescent exit lights and battery powered emergency lights in the corridors. Provide new battery powered LEC	exist lights.
Wiring Devices	
The receptacles and toggle switches are commercial grade 5A and Replace any broken switches and are original to the building. There are 1-2 receptacles per wall. Add additional receptacles to cla Many have been added in surface plastic raceway. required.	
Fire Alarm System	
There is a Simplex 4002 conventional zoned fire alarm system. The control panel is located in the Maintenance Room, pull stations are by all exterior doors, horn appliances and smoke detectors are in the corridors, no horn devices are in open classrooms, and no duct smoke detectors are in the air handling units operating at 2000 CFM or greater.	h a new
Clock System	
There is a Primex central wireless master clock system. Clocks are battery powered. There are analog clocks in the classrooms, offices, Provide additional clocks as n and other public areas.	equired.
Intercom System	
There is a Rauland Telecenter intercom system located in the Health Room. There are recessed ceiling mounted speakers in the corridors and classrooms, which have push to call buttons. The bell replace old intercom speakers system is toned through the speakers.	
Phone System	
There is a Mitel SX-2000 LIGHT analog PBX phone system located in the server room. The phone cabling is CAT5 and is routed back Provide CAT6 wiring for new pto the server room and punched down on wall mounted voice accommodate the future VoIP phwiring blocks.	



SAUKVILLE ELEMENTARY SCHOOL: BUILDING SYSTEMS SUMMARY

Saukville Elementary School	Analysis	Recommendations
Electrical		
Data System		
	The MDF data rack is located in the server room with floor mounted data racks. It distributes fiber optic cable to wall mounted enclosed IDF data racks. The data cable is CAT6 which is routed to patch panels in the data rack.	Additional data can be added. If an addition would require that the data cable have a total installed length of over 300 feet, then an additional IDF data rack will be required.
CATV System		
	There is a CATV service to this building. Splitters are located in the corridor ceiling in classrooms. There is a CATV jack and a ceiling mounted projector or smart board in each classroom.	Additional CATV jacks can be added.
Security System		
	There is a Radionics security system located in the Maintenance Room. The system has motion sensors in the corridors.	Additional security devices can be added.
CCTV System		
	An IP based CCTV system was added to exterior of building and is in good working order.	Add a IP based CCTV system to the interior of the building.
Access Control System		
	There is a Brivo door access control system for this building. There are electric strikes on 7 exterior doors. There are FOB readers at each door.	Additional doors can be added to this system.